

READ ME FIRST!

CONVEX VECLIB V4.0.1

Document No. 740-001118-204

A bug fix has been made in VECLIB since the V4.0 release, resulting in a VECLIB V4.0.1 release. An error in some of the fast Fourier transform routines caused a program to abort under certain circumstances on C220, C230, and C240 processors. This error does not cause problems on C1 and C210 processors. This bug has been fixed in VECLIB V4.0.1.

This change affects the version of the software that you are receiving. If you are receiving VECLIB for the first time or if you have already received and loaded VECLIB V4.0, then load VECLIB V4.0.1 in accordance with the VECLIB V4.0 Installation Procedures (Document No. 740-002318-203). The contents of the VECLIB V4.0.1 software distribution are described in the following table.

CONVEX VECLIB Software

ITEM	QTY	TYPE	PART NUMBER	DESCRIPTION	FORMAT
1.	1	Mag	740-001915-204	CONVEX VECLIB, V4.0.1	Installsw

