

## **SPP-1200/1600 and SPP-2X00 (S and X Class) Year 2000 Requirements**

This document provides details for ensuring Year 2000 compliance on Hewlett Packard SPP-1200, SPP-1600 and SPP-2X00 (S and X Class) systems. The current version of this document can be found in the following locations:

**<ftp://convex.com/tac/doc/Year2000.ps>**

**<http://www.convex.com:90/year2000>**

The table on the following page provides a complete list of hardware and software requirements for all SPP-UX based systems. Any layered products not explicitly called out on this list have no additional Year 2000 requirements beyond the base software product.

### **Obtaining Year 2000 Compliant Software and Patches**

Full product releases for all SPP-UX software are automatically shipped to all systems under maintenance when the software is released. If you need a full release of any SPP-UX based products please contact your local sales office. Customers not currently under maintenance are entitled to a copy of all software required for Year 2000 compliance free of charge.

All patches described in this document, with the exception of HP-UX Year 2000 Patches (covered below) can be obtained electronically from the following locations:

Via SD/UX (swinstall/swcopy) directly from the public software depot:  
**<convex.com:/depot>** (e.g. `/usr/sbin/swinstall -s convex.com:/depot`)

Via anonymous ftp from:  
**<ftp://convex.com/tac/patches/Year2000>**

If you do not have usable access to these systems via the Internet you may request physical DAT tapes containing any of the above software by contacting the Technical Assistance Center at 1-800-952-0379. You may also contact the TAC to request tapes containing specific HP-UX patches if you are unable to obtain them from the following location.

### **Obtaining HP-UX Year 2000 Patches**

The following Web servers contain HP-UX Year 2000 information:

*Main HP Year 2000 Web Server*  
**<http://www.hp.com/year2000>**

*HP-UX specific Year 2000 patch information*  
**<http://www.software.hp.com/products/Y2K/index.html>**

**SPP-1200/SPP-1600**
**SPP-2X00 (S and X Class)**

<b>Hardware Requirements</b>	
<b>Teststation</b>	
<ul style="list-style-type: none"> <li>• 2G System Disk*</li> <li>• 32MB Memory*</li> </ul>	<ul style="list-style-type: none"> <li>• N/A†</li> </ul>
<b>System</b>	
<ul style="list-style-type: none"> <li>• N/A†</li> </ul>	<ul style="list-style-type: none"> <li>• N/A†</li> </ul>
<b>Software Requirements</b>	
<b>Teststation</b>	
<ul style="list-style-type: none"> <li>• HP-UX 10.20*</li> <li>• HP-UX 10.20 Year 2000 Patches*</li> <li>• SPP 1200/1600 Teststation 5.3.1*</li> </ul>	<ul style="list-style-type: none"> <li>• HP-UX 10.20‡</li> <li>• HP-UX 10.20 Year 2000 Patches</li> <li>• SPP-2X00 Teststation 5.3.1</li> </ul>
<b>System</b>	
<ul style="list-style-type: none"> <li>• SPP-UX 5.3</li> <li>• Environment Patch 5.3.128</li> </ul>	<ul style="list-style-type: none"> <li>• SPP-UX 5.3</li> <li>• Environment Patch 5.3.128</li> </ul>
<b>Optional Products§</b>	
<ul style="list-style-type: none"> <li>• C++ Compiler Patch V11.0.2.1</li> <li>• Fortran77 Patch V1.2.6</li> <li>• Fortran90 Patch V1.1.133</li> <li>• NQS+ Patch V2.3.134</li> </ul>	<ul style="list-style-type: none"> <li>• C++ Compiler Patch V11.0.2.1</li> <li>• Fortran77 Patch V1.2.6</li> <li>• Fortran90 Patch V1.1.133**</li> <li>• NQS+ Patch V2.3.134</li> </ul>

\* The following upgrade kit contains a complete set of all necessary hardware and pre-loaded software. Customers under a current support agreement will receive instructions for obtaining the kit when it is available. Customers not covered under a current support agreement should contact their local HP Sales Office for pricing and ordering information.

<u>Part Number</u>	<u>Description</u>	<u>Availability</u>
A4802-70001	Hardware Upgrade Y2K Kit	November 5, 1998

† There are no requirements beyond the originally shipped equipment.

‡ All SPP-2X00 teststations were shipped with HP-UX 10.20 pre-installed.

§ Any optional product not listed has no specific requirement beyond the base product for Year 2000 compliance. These patches are only required if the base product is installed and in use on the system.

\*\* Fortran90 V2.0 does not require patching for Year 2000 compliance.