

PICK LIST AND PRINT/BIND INSTRUCTION

COURSE
5707R150

R150 Uniformance Desktop

MODULE		ORDER	PSC Impr Count	NOTES
5707 cover	5707 cover	1	2	
M5707R150	5707 R150 Course Description and Modules	2	4	R150
P51750	PHD Outline	3	10	
TAB1		4	0	
P51751	PHD R140 Introduction	6	13	
TAB2		7	0	
P51752	PHD Data Processing Overview	8	38	
14287L	Honeywell TotalPlant Support Online Knowledge Base	9	1	R150
CPN-9902L	Customer Priority Notification #9902	10	2	R150
TAB3		11	0	
P51763	PHD Menu Overview	12	13	
TAB4		14	0	
P51753	PHD Tag configuration and Tuning	15	29	
TAB5		16	0	
P51756	PHD Virtual (Calculation) Tags	17	31	
TAB6		18	0	
P51765	PHD Manual Input, Data Put, and Data Routing	19	22	
TAB7		21	0	
P51754	PHD Management and Support	22	30	
tab8		23	0	
P51778	PHD/Oracle Backup Strategies	24	26	
TAB9		25	0	
P51759	Real-Time Data Interface Management	26	28	
TAB10		27	0	
P51755	PHD Tag Load - Part 1	28	56	
TAB11		29	0	
P51780	Overview of Uniformance Client	30	19	R140
TAB12		32	0	
P51772	Overview of Uniformance Application Server	33	13	
TAB13		34	0	
P51769	Implement Tag Database Synchronization	35	23	
TAB14		36	0	
P51771	Overview of Rel2PHD and PHD2Rel	37	35	
TAB15		38	0	
P51764	PHD Security	39	24	
P517641L	Configure PHD Security Training Exercise 1	40	4	R150

PICK LIST AND PRINT/BIND INSTRUCTION

COURSE
5707R150

R150 Uniformance Desktop

MODULE		ORDER	PSC Impr Count	NOTES
P517642L	Implement Integrated NT Security for Uniformance Training Exercise 2	41	12	R150
P517643L	Remove PHD Security from Training System Training Exercise 3	42	3	R150
Print/Bind Instructions:		Total	438	

8 ½ x 11, Insert tabs, Laminate front and back, coil bind – clear, individually shrink wrap,